

EMERGENCY PURCHASE JUSTIFICATION SHEET

DATE: 08/30/16

PURCHASE ORDER NUMBER: 53923

SUPPLIER NAME: Sulzer Pump Service (US) Inc.

DESCRIPTION OF MATERIAL AND/OR SERVICES: Repair 501T Turbine Shaft rub

SINGLE SOURCE JUSTIFICATION:

The repairs for the 501T Turbine Shaft ordered on PO #53923 is necessary because of failure that happened on August 19, 2016 to the turbine Driver, which impairs normal operations of the Davis Count Energy Recover Facility (DERF). While the steam turbine drive is nonoperational electric backup pumps will be used to provide water delivery to the boiler. Continued use of the electric pumps will require the facility to purchase grid power beyond our current contract at very high cost. Bringing the steam driven pump back into service as quickly as possible is in the best interest of the District. Sulzer Pump Service has given us a three to four-week repair time frame with an expedite shipment to Los Angeles, CA.

APPROVAL:



Nathan Rich